



The Copenhagen Forensic Genetic Summer School
Advanced Topics in STR DNA Analysis
June 27-28, 2012





NIST
National Institute of Standards and Technology

CE Troubleshooting

Mike Coble and Becky Hill

NIST Applied Genetics Group
National Institute of Standards and Technology
Gaithersburg, Maryland




Bruce McCord's *Profiles in DNA* Article

PROFILES IN DNA Volume 6 (2), Sept 2003, pp. 10-12

TECH TIPS

Troubleshooting Capillary Electrophoresis Systems

By Bruce McCord
Associate Professor of Forensic Chemistry, Ohio University, Athens, Ohio

The key to producing good DNA separations is to understand the principles underlying the injection, separation and detection of each allele.


INTRODUCTION
The development of capillary electrophoresis (CE) has played a key role in bringing about the modern application of DNA typing. Forensic laboratories are the beneficiaries of this new technology, but many practitioners are not fully aware of the underlying principles of the CE system. This article attempts to address the important issues in CE separations to aid analysts in troubleshooting problematic separations. The key to producing good DNA separations is to understand the principles underlying the injection, separation and detection of each allele. These points are addressed below.

SEPARATION
DNA analysis by CE is performed using entangled polymer buffers (Figure 1). These buffers can be easily pumped into a capillary prior to a separation and pumped out at its conclusion, providing a fresh separation matrix for each run. A typical buffer for forensic DNA separation contains 4% polydimethyl acrylamide (pDMA), buffered to pH 8

Deciphering Artifacts from the True Alleles


Biological (PCR) artifacts

Stutter products




D3S1358

Incomplete adenylation



D8S1179

STR alleles



Bailey, J.M. (2005) Forensic DNA Typing, 2nd Edition, Figure 15.4, © Elsevier Science/Academic Press

Applied Biosystems

Forensic News

October 2007 FAS Corner

http://marketing.appliedbiosystems.com/images/forensic/volume11/docs/52808_FN_FAS_r3.pdf


Troubleshooting Amplification and Electrophoresis of the AmpFSTR® Kits

One of the key responsibilities of our Human Identification Field Application Specialists is to troubleshoot results obtained using any of the AmpFSTR® kits on any Applied Biosystems validated instrument platform.

Troubleshooting Electrophoresis

Below are some common observations that may be seen during electrophoresis of AmpFSTR® kit PCR products:

- Spikes/Extraneous peaks
- No signal or low signal
- Loss of resolution
- Arcing
- Low reproducibility
- Contamination
- Baseline issues
- Poor peak morphology




Sample Issues


- Formamide Conductivity
- Excessive salt in sample due to evaporation
- Metal ion contamination
- Sensitivity issues with Microcon cleanup (salt removal)
- Dye "blobs" – artifacts from primer synthesis


Golden Gate Effect

Attributed to poor formamide



Dye/Sample	Peak	Minutes	Size	Peak Height	Peak Area	Data Point
R, 1	7.29	75.00	380	3201	2735	
R, 2	8.18	100.00	379	3119	3057	
R, 3	9.52	139.00	307	3006	3575	
R, 4	9.69	150.00	309	3232	3959	
R, 5	10.19	180.00	248	3144	3820	
R, 6	11.51	200.00	205	2864	4318	
R, 7	13.01	249.00	192	1950	4877	
R, 8	14.67	300.00	273	2818	5501	
R, 9	15.83	340.00	299	3191	5928	
R, 10	16.17	350.00	400	4338	6092	
R, 11	17.67	400.00	565	6049	6527	
R, 12	19.08	450.00	695	6718	7158	





December 21, 2007

Applied Biosystems
an Applied Biosystems, Inc.

850 Lincoln Centre Drive
Foster City, CA 94404
T 800.521.8607 F 650.5
www.appliedbiosystems.com

What does ABI Say?

Dear Valued Customer,

We are writing this letter in response to inquiries from customers regarding artifact peaks that appear as "shadow peaks" to true DNA peaks observed in the electropherogram. In most cases, these artifacts appear to be the most prevalent in the dye channel corresponding to the size standard and do not affect accurate sizing of the size standard peaks.

An example electropherogram is shown below:

Electropherogram showing shadow peaks in GS500 ROX

The occurrence of these "shadow peaks" has been replicated at Applied Biosystems. We also observed during the testing process that higher shadow peak heights result from longer injection times. We are in the process of investigating the occurrence of these "shadow peaks" to determine the root cause and address the issue.

Applied Biosystems is committed to providing the highest quality products available for use in DNA typing. Thank you for your valued feedback. Your input is extremely valuable to us in our efforts to improve the quality of our products. Please feel free to contact HED Technical Support at 1.888.821.4310 (4443), #1 for further information.

What is it really?
 Incomplete denaturation of standard due to excessive salt in sample or in formamide

**ds DNA migrates faster and over time with this set of runs
 ds DNA replaced the ssDNA**

Shadow peaks

Shadow peaks result from incomplete denaturation or from rehybridization.

dsDNA migrates faster than ssDNA and the extra peaks appear ahead of the main peaks

They are most visible in the size standard but can appear in other dye lanes

single shadow peaks appearing to left of allelic peaks

Hybridization due to leftover primers

Artifacts in the Powerplex 16 amplification of the vWA locus. Two artifacts occur.

1. The doubled peaks and shoulders are the result of primer hybridization to PCR amplicons not adenylation.
2. The additional peak eluting earlier is the result of renaturation of the ssDNA amplicon.

The first two slides are performed on a 3100 system. The second is on a 310. The 310 denatures the samples better due to its heat plate and eliminates the splitting, however, the dsDNA product is still present.

Recent Promega Solution to Eliminating vWA Artifacts in PowerPlex 16 Results



Post-injection hybridization of complementary DNA strands on capillary electrophoresis platforms: A novel solution for dsDNA artifacts


Robert S. McLaren^{a,*}, Martin G. Ensenberger^a, Bruce Budowle^b, Dawn Rabbach^a, Patricia M. Fulmer^a, Cindy J. Sprecher^a, Joseph Bessetti^a, Terri M. Sundquist^a, Douglas R. Storts^a

^a Promega Corporation, 2800 Woods Hollow Road, Madison, WI 53711, United States
^b Federal Bureau of Investigation, 2501 Investigation Parkway, Quantico, VA 22135, United States
 Received 5 February 2008; received in revised form 11 March 2008; accepted 13 March 2008

Several laboratories have reported the occurrence of a split or n-1 peak at the vWA locus in PowerPlex 16... The root cause of this artifact is post-PCR reannealing of the unlabeled, unincorporated vWA primer to the 30-end of the tetramethylrhodamine (TMR)-labeled strand of the vWA amplicon. **This reannealing occurs in the capillary post-electrokinetic injection.** The split peak is eliminated by incorporation into the loading cocktail of a sacrificial hybridization sequence (SHS) oligonucleotide that is complementary to the vWA primer. The SHS preferentially anneals to the primer instead of the TMR-labeled strand of the vWA amplicon...




Impact of Added Oligos to vWA Amplicon Peaks



From Figure 5
 McLaren et al. (2008) Forensic Science International: Genetics 2: 257-273



Dye Blobs and their Removal



NIST Y-STR 20plex assay
 Butler, J.M. (2005) Constructing STR multiplex assays. *Methods in Molecular Biology: Forensic DNA Typing Protocols* (Carracedo, A., ed.), Humana Press: Totowa, New Jersey, 297-53-66.



Why MiniElute increases peak heights


- QIAGEN MiniElute **reduces salt levels in samples causing more DNA to be injected**
- **Requires setting a higher stochastic threshold** to account for the increased sensitivity



Smith, P.J. and Ballantyne, J. (2007) Simplified low-copy-number DNA analysis by post-PCR purification. *J. Forensic Sci.* 52: 820-829

Stochastic Effects and Thresholds

Regular Injection Injection Following Desalting (MiniElute)



When PCR amplifying low levels of DNA, allele dropout may occur

Allele failed to amplify

Stochastic threshold must be raised

Allele failed to amplify

False homozygote


External Factors

- Room temperature
 - Variations in room temperature can cause mobility shifts with band shifts and loss of calibration
 - Temperature is also important due to effects of high humidity on electrical conductance
- Cleanliness
 - Urea left in sample block can crystallize and catalyze further crystal formation causing spikes, clogs and other problems.
 - Best bet is to keep polymer in system and not remove or change block until polymer is used up.

Temperature effects

- Viscosity – mobility shift
 - $\mu_{ep} = q/6\pi\eta r$
- Diffusion – band broadening
 - $\xrightarrow{\text{DNA}}$
- Conformation – DNA size based sieving
 - vs $\mu_{ep} = q/6\pi\eta r$
- Current – Power
 - $P = VI = I^2R$
 - Increased current \rightarrow internal temperature rise \rightarrow diffusion \rightarrow band broadening


Effect of temperature on allele size





Slope is 0.14 bases/degree centigrade
 Therefore a small change in temperature has a big effect
 (A 1-2 degree shift in temperature of the heat plate can produce an OL allele)


Hartzell, B., et al. (2003). Response of short tandem repeat systems to temperature and sizing methods. *Forensic Science International*, 133, 228-234.

D18S51











“OL allele re-injected”



And the 250 peak...



Monitoring Room Temperature Over Time





Refrigerator and freezer monitoring


Temperature Probes


Frig/Freeze Monitors S240
 #DT-23-33-80 – USB Temperature Datalogger
 PLUS Software \$79.00 (#DT-23-33-60)

Room Monitors, # DT-23039-52 – USB
 Temperature-Humidity Datalogger \$91.00
 (Cole Parmer, Vernon Hills IL)

Room temperature monitoring








What to do if calibration is lost?
The 310 only calibrates to the first run ladder
this ladder sample may have been run at a different temperature!

- If protocol permits
 - Go to the next ladder
 - Rerun sample
 - Check current
 - Check allelic ladder
- Always check the size standard
 - Look for extra bands
 - Check peak height
 - Check parameters and alignment

Cleanliness

- Urea sublimates and breaks down to ionic components - these find a path to ground
- Similarly wet buffer under a vial creates paths to ground
- Capillary windows must be clear or matrix effects will occur
- Laser will often assist in this process
- Vial caps will transfer low levels of DNA to capillary




Instrumental Factors

- Optical System
 - Sensitivity changes with age, capillary diameter, capillary cleanliness, instrument calibration
- Fluidic System
 - Effects of bubbles, dust, urea crystals, leaks in syringe and capillary ferrule
- Matrix Calculations
 - Changes in buffer, optics, sample dye can alter the software calibrations
- Capillary Problems
 - Chemisorbed materials on capillary surface can produce osmotic flow, DNA band broadening and inconsistent resolution (meltdowns)

Issues with the Optical System

- Argon Ion lasers outgas and eventually loose intensity; **take note of laser current and monitor it over time**
- Fluorescence expression:
 $I_f = I_0 k b C \phi$ - changes in input intensity: I_0
 - changes in capillary diameter: b
 - cleanliness of capillary, optics: k
- All these things directly affect peak RFUs, however, baseline noise is more affected by detector.
- **Thus by monitoring signal to noise, you can get a better picture of your optical system.**


The Detection Window




Make sure that the capillary window is lined up (if it is not, then no peaks will be seen)


Window may need to be cleaned with ethanol or methanol

Review Start of Raw Data Collection



Little spikes indicate need to change buffer... check current





- Buffer Issues**
- The buffer and polymer affect the background fluorescence-affecting the matrix
 - Urea crystals and dust may produce spikes
 - High salt concentrations may produce reannealing of DNA
 - High salt concentrations affect current
 - Low polymer concentrations affect peak resolution

Beware of Urea Crystals




Urea crystals have formed due to a small leak where the capillary comes into the pump block

Urea sublimates and can evaporate to appear elsewhere


Use a small balloon to better grip the ferrule and keep it tight

Pump block should be well cleaned to avoid problems with urea crystal formation

Remove all bubbles from the channels




Bubbles in the channels can prevent flow of ions and are usually exhibited by zero current when the voltage is applied




Matrix Problems


- A poor matrix can lead to raised baseline and therefore calling of too many peaks
- Larger sized alleles will not be identified as peaks because the GeneScan table for a particular dye color has filled up





"Data gap" - phenomenon STRs





What we call "melt downs" ... probably due to an incompletely filled capillary












- ### Meltdowns may be the result of
- Bad formamide
 - Excess salt in sample/renaturation
 - Water in the polymer buffer
 - **Syringe leak** or bottom out
 - Poisoned capillary
 - Conductive polymer buffer due to urea degradation
 - Crack/shift in capillary window
 - Detergents and metal ions

- ### Maintenance of ABI 310/3100/3130
- Syringe – leaks cause capillary to not fill properly
 - Capillary storage & wash – **it dries, it dies!**
 - Pump block – cleaning helps insure good fill
 - Change the running buffer regularly
- YOU MUST BE CLEAN AROUND A CE!**

Current Spikes


Generally appear in all lanes and are sharper than regular peaks
 These are a natural consequence of the application of high voltage in CE
 and may also be caused by particulates in buffer.



A permanent loss of resolution may mean

- Adsorptive sites on a capillary
- Initiation of electroosmotic flow
- Conductivity changes in buffer/polymer
- Wrong buffer formulation
- Bad formamide or internal lane standard
- Contaminated syringe

Loss of Resolution




Gradual broadening of peaks as the molecular weight of the data increases results in a sample that fails to genotype and can be caused by the following:

- Poor water quality
- Poor quality system reagents
- Insufficient capillary filling
 - Leak in the system fittings
- Air in the system
 - Bubbles
- Impurities
 - Protein, salts
 - Detergents
- Poor/exhausted array
- Poor instrument maintenance


Attention to detail with regard to instrument maintenance and remaining aware of when an array may need to be replaced will help to avoid such issues.


http://marketing.appliedbiosystems.com/images/forensic/volume11/docs/52808_FN_FAS_r3.pdf



- ### Troubleshooting benchmarks
- **Monitor run current**
 - Observe syringe position and movement during a batch
 - Examine ILS (ROX) peak height with no sample
 - Observe "250 bp" peak in GS500 size standard
 - Monitor resolution of TH01 9.3/10 in allelic ladder and size standard peak shapes
 - **Keep an eye on the baseline signal/noise**
 - Measure formamide conductivity
 - Reagent blank – **are any dye blobs present?**
 - See if positive control DNA is producing typical peak heights (along with the correct genotype)

- ### Measurement of Current
- $V/I = R$ where R is a function of capillary diameter, [buffer], and buffer viscosity
 - In a CE system the voltage is fixed, thus changes in resistance in the capillary will be reflected in the current observed
 - Air bubbles, syringe leaks, alternate paths to ground, changes in temperature, changes in zeta potential, and contamination, will be reflected in the current
 - A typical current for a CE system with POP4 buffer is **8-12 μ A** (microamps)





Measuring Formamide Conductivity

(not this way)


The key is to measure the bottle when it comes in or buy the good stuff and immediately pipette it out into small tubes with or without ROX already added. Then freeze the tubes.

Do not ever open a cold bottle of formamide. Water will condense inside and aid in the formation of conductive formic acid.


Comments on Sample Preparation

- Use high quality formamide (<math><100 \mu\text{S}/\text{cm}</math>)
- Denaturation with heating and snap cooling is not needed (although most labs still do it...)
- **Post-PCR purification reduces salt levels** and leads to more DNA injected onto the capillary

Importance of Sample Preparation



Peak tailing and wider peaks indicative of an injection with a salty sample




Same DNA sample prepared in fresh, high-quality formamide

Data from Amy Decker (NIST, now AFDL)


Troubleshooting Hint: Examine Internal Size Standard

Comparison of GS500 LIZ Size Standard

Sample diluted in Old Hi-Di Formamide



Sample diluted in Fresh Hi-Di Formamide



Data from Amy Decker (NIST, now AFDL)

ABI Solution to Polymer Problem

The preliminary results of our investigation suggest that recent lots of 310x POP4 polymer may be contributing to some of the reported incidents and, as such, additional efforts have focused on polymer as a potential root cause. While our root cause investigation is still on-going, a cross-functional team has been established to review all polymer testing data. The team meets regularly and is actively looking into aspects of polymer manufacturing and the relationship of polymer to other consumables that may impact data quality.

As a proactive effort, the rate of polymer production has been increased in order to help meet customer demand and all recently released POP4 polymer has been subjected to additional functional testing to ensure polymer performance. We have confirmed that all released lots of POP4 polymer have passed internal quality control testing.

We are also pleased to inform you that most reported incidents have been successfully resolved through the efforts of the local support teams utilizing the following procedure:


- Flush the system 10 to 15 times with warm (40°C) deionized system water wash prior to array/polymer replacement. Using a high purity bottled water source may help to eliminate water as a potential contributing factor.
- The warm water wash should be followed immediately by replacement of the capillary array and consumables kits (e.g. polymer, buffer and water) as advised by your Applied Biosystems Field Applications Specialist.
- In extreme cases, replacement of the lower block or front end may also be required to recover performance.

The most recent reports are specific to low quality data on the 3100 instrument platform. Internal testing indicates that packaging is contributing to this low quality data. We are focusing our efforts on variation in packaging between our different bottle configurations. To help minimize packaging variation we are evaluating an alternative bottle plastic for 3100 POP4, which will be more similar to the 3130 POP4 bottle configuration. We are also closely monitoring shipping conditions to determine any potential impacts from shipping.

Effect of contaminant in reference sample

Contamination results in problems in subsequent analyses


Effect is transitory



Data from Bruce McCord (Florida International University)

Sample Renaturation (minor dsDNA peaks running in front of primary ssDNA STR alleles)

ROX Artifacts
Comparison Casework Blood Sample




Data from Peggy Phillon (RCMP)

Why dsDNA migrates through CE capillary faster than ssDNA...


- DNA molecule separation depends on interactions with the polymer
 - Higher polymer concentration (or longer polymer molecules) permits more polymer interactions and provides better resolution (i.e., POP-6 vs POP-4)
- **Single-stranded DNA (ssDNA) is more flexible than double-stranded DNA (dsDNA)** and therefore moves more slowly through the capillary because it is interacting with polymer strands more


dsDNA vs ssDNA CE Migration


- If a small amount of the complementary strand re-hybridizes to the labeled STR allele strand, then a little peak will be seen in-front of each internal lane standard peak and



More Sample Renaturation







Conclusion:
Troubleshooting is more than following the protocols

It means keeping watch on all aspects of the operation

1. Monitoring conductivity of sample and formamide
2. Keeping track of current and syringe position in log.
3. Watching the laser current
4. Watching and listening for voltage spikes
5. Monitoring room temperature and humidity

Thank you for your attention

Acknowledgments: NIJ & FBI Funding



Contact Information

Becky Hill
Research Biologist
becky.hill@nist.gov
301-975-4275

Mike Coble
Research Biologist
michael.coble@nist.gov
301-975-4330

Our team publications and presentations are available at:
<http://www.cstl.nist.gov/biotech/strbase/NISTpub.htm>
